

MAGNETOM

# Safety-Related Tests Report System

Safety-Related Tests according to IEC 62353

**Customer:** ТОВ "МЕДИСТАР"

**Address:** Пр-т С. Бандери, 17/1  
04073 Київ

**Fax / E-Mail:**

**Fax / E-Mail:**

**Department:**

**Room:**

**Material-No.:**

**Serial-No.:**

**Contract-No.:**

**Expire date:**

**Order-No.:**

**System - ID:**

Avanto  
Espree

The instructions M6-020.833.05.02.XX are required for this protocol

## Final Evaluation

Initial Measurement  Repeat Measurement

The evaluation was performed after completing all work steps.

- No deficiencies
- Slight deficiencies that require corrective measures: These must be recorded under Remarks.
- Significant deficiencies: The safety of the system is no longer assured. If these deficiencies are not corrected, there is a "risk for patients, users or third parties".

Signature:



Date: 07.01.2025

Tester:

If required by country-specific regulations:

The customer or a representative has taken note of the result of the evaluation of the system condition.



Date: 07.01.2025

Signature:

Remarks:

--

СТАРШИЙ ІНЖЕНЕР  
ПОТАПЕНКО С.Ю.